



Since 1968

HYTORC AVANTI-50
PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN					PRESSURE IN
PSI	FT. LBS.	KGM	NM	BAR	
1500	7180	993	9733	104	
1600	7667	1060	10393	110	
1800	8641	1195	11714	124	
2000	9615	1330	13034	138	
2200	10622	1469	14399	152	
2400	11629	1608	15764	166	
2600	12636	1748	17129	179	
2800	13643	1887	18494	193	
3000	14650	2026	19860	207	
3200	15593	2157	21138	221	
3400	16536	2287	22416	235	
3600	17479	2417	23695	248	
3800	18422	2548	24973	262	
4000	19365	2678	26251	276	
4200	20272	2804	27481	290	
4400	21179	2929	28710	304	
4600	22086	3054	29940	317	
4800	22993	3180	31169	331	
5000	23900	3305	32399	345	
5200	24753	3423	33555	359	
5400	25606	3541	34711	373	
5600	26459	3659	35868	386	
5800	27312	3777	37024	400	
6000	28165	3895	38180	414	
6200	28988	4009	39296	428	
6400	29811	4123	40412	442	
6600	30634	4237	41527	455	
6800	31457	4351	42643	469	
7000	32280	4464	43759	483	
7200	33033	4568	44780	497	
7400	33786	4673	45800	511	
7600	34539	4777	46821	524	
7800	35292	4881	47842	538	
8000	36045	4985	48863	552	
8200	36651	5069	49684	566	
8400	37257	5153	50506	580	
8600	37863	5236	51327	593	
8800	38469	5320	52149	607	
9000	39075	5404	52970	621	
9200	39744	5497	53877	635	
9400	40413	5589	54784	649	
9600	41082	5682	55691	662	
9800	41751	5774	56598	676	
10000	42420	5867	57505	690	

12420 TEXACO ROAD Houston, Texas 77013 713-453-6677 www.hyorctexas.com

This chart supercedes all prior version regarding this tool

03/31/2008